

Clock  
 20 days  
 Dec - 28<sup>o</sup>

B7 310V  
 160 mc  
 Fil. 7.2

Time		ua	10-18-38			
Time	ua	Time	ua	Time	ua	
110P	125					
111	127	135	119	159	111	
112	121	35	119	200	110	
113	119	37	119	07	110	
114	117	38	120	02	111	
115	119	39	120	03	113	
116	113X	40	120	04	113	
117	118	41	120	05	115	
118	118	42	119	06	115	
119	118	43	116	07	116	
120	118	44	115	08	116	
121	119	45	116	09	115	
122	119	46	115	10	114	
123	119	47	116	11	115	
124	120	48	116	12	116	
125	120	49	117	13	—	
126	119	50	118	14	116	
127	—	51	118	15	117	
128	115	52	119	16	117	
129	113	53	119	17	118	
130	112	54	119	18	119	
131	112	55	119	19	119	
132	113	56	116	20	116	
133	115	57	115	21	116	
134	117	58	112	22	114	

beginning to rain. Temp. dropping

time sea

223	115
24	116
25	118
26	118
27	119
28	120
29	121
30	123
31	123
32	122
33	125
34	126
35	124
36	105
37	103
38	102
39	103
40	105
41	106
42	108
43	109
44	110
45	-
46	116
47	120

was a change in game due to loose tube clips on a 956.  
 something slipped with a snap. (add 20)

time sea

248	121
49	123
50	126
51	127
52	130
53	131
54	132
55	133
56	135
57	138
58	-
59	142
300	142
301	144
02	145
03	145
04	144
05	145
06	-
07	146
08	-
09	135
10	135
11	138
12	138


Filament too loose, readings high

(add 10)

time sea

313	320
321	142
323	143
331	146
333	144
337	146
341	149
342	151

10-18-38



1500  
1408  
1306  
1204  
1102  
100

110 20 30 40 50 200 10 20 30 40

10-18-38

